

### **Mini-Tower test results**

Luca Latronico INFN Pisa for the TKR subsystem


GLAST International Collaboration Meeting Accademia Nazionale dei Lincei Roma 15-18 September 2003

1



# **Motivations**

- First complete working prototype of flight-like hardware
- 6 Si-layers 5 trays minimal configuration for L1T
- Test specific TKR hardware components and assembly strategies:
- flight Si-Ladders assembly and test
- mechanical Trays assembly
- MCMs (GTFE/GTRC tests), assembly onto trays, bonding
- flex cables
- tower sidewalls and assembly tools
- Test ELX/DAQ components
- Develop EGSE TKR test suite to test, qualify, operate a tower before delivery to I&T
- Develop documentation templates for efficient hands-off to I&T
- Support I&T during integration with CAL
- Data taking with CR and 17MeV VdG gamma





# **History**

First version of minitower built last february/march Main problems to be addressed • MCM:

 instabilities in the GTFE chip required fine-tuning of the low voltage

 bad pitch adapter (too small pads, not flat surface)

bad bias HV insulation

Flex cables and connectors to MCM


Trays were shipped back to INFN and refurbished with new electronics:

- MCM:
- new GTFE chip (G3)
- improved pitch adapter
- HV insulation improved with insertion of a Kapton layer
- New flex cables and connectors


### **Preliminary tests on MCMs**

#### Functional tests from UCSC repeated in Pisa on all bare MCMs

- ✓ GTFE /GTRC register testing
- ✓ Load all possible layer configurations and read few events
- ✓ Inject charge in all channels and look for noisy or dead channels (1 dead ch found)








### **Still missing channels for pitch adapter problems**


left side

right side



#### tracks shift

#### **Bad gluing and planarity**





### Still missing channels for pitch adapter problems


The HV, GND and some channels lines are wrapped around the PCB edge, preventing bonding



### Wrong pitch

• 191 missing wire-bonds to strips

 had to give up redundancy of bias HV connections on border ladders




### **Minitower construction**




# Stacking the trays - sidewalls are reference and support

Cabling each side after opening its sidewall






#### **Complete the stack**



**Complete open structure** 


9

### Just 2 hours later real cosmic events start flowing




# **Noisy strip search**

#### low statistics Occupancy < $10^{-4}$ (LAT-SS-17-5 TKR Level III specs) 13 strips masked



### **Strip Occupancy**

#### 22M evts threshold DAC = 30




1000 Strip umber L. Latronico – TKR subsystem – INFN Pisa

1500

500

### Layer noise occupancy





10

Noise Occupancy for layerX1 (1535 strips)


Noise Occupancy for layerX2 (1511 strips)

10






#### Light leak from the top






### Light leak and leakage current




### **Bad HV connection on border ladder**






GLAST-LAT International Collaboration Meeting, Roma Sept. 15-18 2003 Cosmics - hitmaps

Threshold = 30 DAC, range 0, 13 strips masked. ~ 15000 events collected.







### Conclusions

- TKR Minitower refurbished in one week
- TKR Minitower completely characterized before delivery
- Met specs in terms of efficiency, occupancy
- TKR Minitower delivered to I&T according to schedule
- Integration with CAL at SLAC
- Still problems in mechanics of pitch-adapter (2% channels could not be bonded)
- Residual problems in pitch adapter alignment and MCMs bias lines + inconsistencies with older bias circuit induced bias problems in 2 border ladders
- Still read-out problems (time-out errors) in few events (-1/1000)

#### find more at http://glastserver.pi.infn.it/glast

