

- Deviation from RSDO Catalog Impacts Cost and Schedule
- Original 5 Second to Internet Requirement is High Risk
  - Change to 7 Seconds Should be Reasonable
- 1 ms C&DH Processing Requirement Breaks Vendors Design - \$,\$\$\$,\$\$\$.\$\$
- On-Board Bus Architecture can Improve Response Time


**Response Time Constraints** 




#### BASELINE GLAST C&DH



| Т | IM | EL | INE |
|---|----|----|-----|
| - |    |    |     |



#### LAT and GBM on HIGH RATE BUS



#### DIRECT CONNECT GBM to LAT